

Message

From: Rick Grant [rgrant@oit.umass.edu]
Sent: 1/11/2011 2:54:33 PM
To: 'Lobik Stephen' [slobik@facil.umass.edu]
CC: 'Hanchett, James (DPH)' [James.Hanchett@state.ma.us]
Subject: RE: Morr I/Morr IV Second Floor Plans

Hi, Steve & Jim;

Thanks for the floor plan, Steve. I haven't seen this before but that is not unusual especially if I'm not doing a work order to initially install the jacks.

Leslie said with the pending storm we need to push the work back to Friday. Thursday is a full day of work already and, with the possible loss of tomorrow, it is going to back us up more. We still have an issue with a jack (2-1-10) in Rm N222 that needs resolution. Leslie will get back to me when that has been done. This affects 5-6600. Jack 2-1-17 is available, if that is a possibility.

I am going to work with our Systems Office to get the room numbers changed for those 3 rooms today to help facilitate this work.

Rick

Richard J. Grant
Design Specialist/Customer Service
UMass Telecommunication Services
101 University Drive, Suite B1
Amherst, MA 01002-2376
413.545.2171

From: Lobik Stephen [mailto:slobik@facil.umass.edu]
Sent: Tuesday, January 11, 2011 8:07 AM
To: Rick Grant; Verdi Roxanne
Subject: RE: Morr I/Morr IV Second Floor Plans

Rick,

Attached is the approved plan with new room numbers in red.

Stephen

Stephen Lobik
Capital Project Manager
Facilities & Campus Planning Division
University of Massachusetts
(T) 413-545-6516
(C) [REDACTED]
(F) 413-545-3684
slobik@facil.umass.edu

From: Rick Grant [mailto:rgrant@oit.umass.edu]

Sent: Monday, January 10, 2011 4:06 PM

To: Verdi Roxanne

Cc: Lobik Stephen

Subject: Morr I/Morr IV Second Floor Plans

Hi, Roxanne;

We're having issues with room numbering right where the two second floors meet for Morrill I & Morrill IV. Can you send me both floor plans? Thank you.

Rick

Richard J. Grant
Design Specialist/Customer Service
UMass Telecommunication Services
101 University Drive, Suite B1
Amherst, MA 01002-2376
413.545.2171